U.S. Patent and Trademark Office: U.S. DEPARTMENT OF COMMERCE Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO 7, 401, 211 B2 DATED : July 15, 2008

INVENTOR(S): Sailesh KOTTAPALLI et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4, Line 6 "rescheduling" should be --rescheduling--

KENYON & KENYON LLP MAILING ADDRESS OF SENDER: 333 W. San Carlos, Ste 600 PATENT NO. 7,401,211 B2

Date: July 14, 2009

San Jose, CA 95110 Telephone: (408) 975-7500 Facsimile: (408) 975-7501 Attorney Ref.: 02207/10121

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer. U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

APPLICANTS : Sailesh KOTTAPALLI et al.

SERIAL NO. : 09/751,762

FILED : December 29, 2000

PATENT NO. : 7.401.211 B2

ISSUED : July 15, 2008

FOR : METHOD FOR CONVERTING PIPELINE STALLS CAUSED

BY INSTRUCTIONS WITH LONG LATENCY MEMORY
ACCESSES TO PIPELINE FLUSHES IN A MULTITHREADED.

PROCESSOR

GROUP ART UNIT : 2183

EXAMINER : Daniel PAN

M/S: CERTIFICATE OF CORRECTION BRANCH

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Dear Sir:

We have compared the above patent with the application as filed and have found errors in the printing of the patent. We respectfully request that the enclosed Certificate of Correction on Form PTO-1050 be issued correcting the mistakes set forth therein under authority of 35 U.S.C. \$254.

Application No.: 19/751,762

Certificate of Correction dated: July 14, 2009

Patent No.: 7,401,211 B2 Issued on: July 15, 2008

The errors that appear in the patent are various typographical errors made by the Patent Office and no fee is believed required.

If any fee is required, the Office is hereby authorized to charge any additional fees, or credit any overpayments, to Kenyon & Kenyon LLP, Deposit Account No. 11-0600.

Respectfully submitted,

KENYON & KENYON LLP

Dated: July 14, 2009 By: /Sumit Bhattacharya/

Sumit Bhattacharya (Reg. No. 51,469)

KENYON & KENYON LLP 333 West San Carlos St., Suite 600 San Jose, CA 95110

Telephone: (408) 975-7500 Facsimile: (408) 975-7501